

# Inspection Report (PEO)

R-us4-16458213

## Inspection information



**Product Name:**

Footwear

**Inspection location:**

JinJiang

**Inspection date:**

22/Dec/2016

**Your internal reference number:**

**Reference # / SKU #**

**P/O number:**

**CHI621-2**

**Supplier:**

**Order quantity:**

12750 Pairs

**Actual quantity:**

12750 Pairs

**Container number:**

CAIU 9703541

**Factory cooperation**

Average

**Factory organization**

Average

**Inspector's opinion on the factory**

Average

## Inspection remark

1.Actual loading quantity:12750pairs/12750ctn.

2.PO number on front mark did not respect description from attached: MICKEY-02/MICKEY-03/MICKEY-03.

Actual finding: TENNIS M 2 -2016/ TENNIS M 3 2016 / TENNIS M 3 2016



## 1. Supplier Overview:

**Factory's Location**



**Factory's Gate Picture**



**Warehouse Picture**



**Product Picture in warehouse**



**Loading Area Picture**



**Loading Equipment picture**



## 2. Cargo Information:

Inspector Arrival Time	Loading Starting time	End of the Inspection time
11:30	13:50	15:30

Loading Facility Cooperation:	Good		Average	x	Bad	
-------------------------------	------	--	---------	---	-----	--

Container Size:	20DC		40DC		40HC	x	45' HC	
-----------------	------	--	------	--	------	---	--------	--

Container No	Shipping Seal No
CAIU 9703541	AH60099609

Container Status:	Good	x	Damaged		Seriously damaged	
-------------------	------	---	---------	--	-------------------	--

Expected defects							
Holes	Dents	Moisture	Oil	Paint	Dirt	Smell	Mold
(No)	(No)	(No)	(No)	(No)	(No)	(No)	(No)

Floor Condition:	Good	x	Scratched		Broken	
------------------	------	---	-----------	--	--------	--

Doors Condition:	Good	x	Bad		
------------------	------	---	-----	--	--

If a damage had been found as mentioned above, please input some detailed pictures & comments:  
 (optional, if no, please delete)



### 3. Pallets information:

<b>Palletized Cargo</b>	<b>(No)</b>	<b>Material of the Pallet</b>	<b>N/A</b>
<b>Total Quantity of Pallets loaded:</b>		<b>N/A</b>	
<b>Pallet No From XX To XX:</b>		<b>N/A</b>	
<b>If pallets with 2 different kinds of material or more had been used for the loading, please specify the pallet loading quantity &amp; pallet No from XX to XX for each material:</b>		<b>N/A</b>	

If a solid nature wooden pallet had been found, please input pictures as requested below:

<b>Pallet's Material</b>	<b>Fumigation's Stamp</b>
<b>N/A</b>	<b>N/A</b>





#### 4. Container overall view picture:

**Container Front (Doors)**



**Container Back**



**Container Left Side**



**Container Right Side**



**Container Floor & Joint (inside)**



**Container Wall & Joint (Inside)**





## 5. Product Detailed Information

**Total Quantity:** 12750pairs/12750ctn

Invoice No.	P.O.	Model	Description	Packages (Cartons)	Total Pieces / Pairs	Material
CH1621- 2	MICKEY-02	PPIMT00004	CHILDREN'S SHOES	1035	10350	Textile/sintetica
CH1621- 2	MICKEY-03	PPIMT00023	CHILDREN'S SHOES	120	1200	Textile/sintetica
CH1621- 2	MICKEY-03	PPIMT00022	CHILDREN'S SHOES	120	1200	Textile/sintetica
<b>Total</b>				1275	12750	/

No. of boxes opened for pictures:	3
No. of boxes opened for verification:	3
Total number of boxes opened during the inspection:	6
Does the actual color of product for each reference match the color description on packing list & client's specifications?	(Yes)
For product with the same model & description, is the brand on package the same as the one shown on the product?	(Yes)
Do the quantity and characteristics of the items from the packing list match exactly the inspected items?	(Yes)
Is there any damaged/wet package?	(No)

## 6. Loading Pictures

Container No: **CAIU 9703541**

Container Number



Empty Container



1<sup>st</sup> loading Line of Container



Half Loaded Container



3/4 Container loaded



Full Container Loaded






Right door closed (the door with container # & Inspector stands by the container)



2 doors closed with clear container#



Shipping seal locked on container



Shipping seal number





## 7. Detailed Pictures

Product : PPIMT00004


Carton over view



Carton front view



Carton side view



Carton opening view







**SafeLink**  
INSPECTIONS & COMPLIANCE

Product details



Product details



Product details



Product details



Product details



Product details




Product details

Product details



Product details

Product details



Product details

Product details



Product details

Product details





Product details

Product details



Product details

Product details



Product details

Product details



Product details



Product details




Product details



Product details



Product details



Product details





Product details



Product details



Product details



Product details



Product : PPIMT00023





Carton over view



Carton front view



Carton side view



Carton opening view






Product details



Product details



Product details



Product details



Product details



Product details



Product details




Product details







Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details




Product details






Product details



Product details



Product details



Product details



Product details



Product details





Product :PPIMT00022


Carton over view



Carton front view



Carton side view



Carton opening view





Product details



Product details



Product details



Product details



Product details




Product details



Product details

Product details





Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details



Product details




Product details





Product details



Product details



Product details



Product details



Product details



Product details





Additional pictures

